Published in the Jag Bani (Patiala Bani) on 04 Dec 2025.

## **TENDER NOTICE**

## YADAVINDRA PUBLIC SCHOOL PATIALA 147001

Invites quotations by 10<sup>th</sup> Dec 2025 for repair to MS structure of Lighting Towers (height approx. 50'). Details can be downloaded from school website www.ypspatiala.in .

# YADAVINDRA PUBLIC SCHOOL, PATIALA BOQ : REPAIR TO TWO LIGHTING TOWERS INSTALLED IN THE STADIUM

#### Date

| Ser | Nature of work                                  | AU   | Qty | Rate                                  | Amount |
|-----|---|------|-----|---------------------------------------|--------|
| No  |   |      |     |                                       |        |
| 1   | Removal of rusted MS sheet and supporting       | Sqft | 340 |                                       |        |
|     | MS pipes of repair way at height of 50' approx  |      |     |                                       |        |
|     | and stacking at appropriate place as instructed |      |     |                                       |        |
|     | at site.  |      |     |                                       |        |
| 2   | Supply, hoisting, cutting to required size and  | Rft  | 104 |                                       |        |
|     | fixing of intermediate support MS pipe about 4' |      |     |                                       |        |
|     | in length, dia 3" Heavy duty . To be welded     |      |     |                                       |        |
|     | with main structure member of repair bay at     |      |     |                                       |        |
|     | height 50' approx                               |      |     |                                       |        |
| 3   | Supply, hoisting, cutting to required size and  | Sqft | 340 |                                       |        |
|     | fixing of MS sheet 3mm thick. To be welded      |      |     |                                       |        |
|     | with main structure member of repair bay at     |      |     |                                       |        |
|     | height 50' approx                               |      |     |                                       |        |
| 4   | Painting one coat of epoxy primer and two       | Sqft | 680 |                                       |        |
| 4   | coats of Aluminium Paint                        | Sqit | 000 |                                       |        |
|     |   |      |     | <b>3</b>                              | 0      |
|     | Total including GST                             |      |     | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | ľ      |
|     |   |      |     |                                       |        |

### **Note**

- 1 Repair work is to be carried out at approx 50' height
- 2 Rates coated shall include the cost of scaffolding /Hydra crane
- 3 Safety precaution measures to be strictly adhered to.
- 4 School authorities shall not be responsible for any kind of mishap
- 5 Electric supply shall be provided by the school.
- 6 Connecting lead for welding set /cutting machine shall be provided by the contractor and he must ensure that this wire is properly insulated.
- 7 Ensure that electric supply of lighting towers is cut off before mounting it for repair.